Certificate SG00/00050



The management system of



PT Venturindo Jaya Batam

SM Business Centre Blok B, Jalan Yos Sudarso Batu Ampar, Pulau Batam 29432 Indonesia

has been assessed and certified as meeting the requirements of

ISO 9001:2015

For the following activities

The scope of registration appears on page 2 of this certificate.

This certificate is valid from 13 April 2021 until 12 April 2024 and remains valid subject to satisfactory surveillance audits. Recertification audit due a minimum of 60 days before the expiration date.

Issue 11. Certified since 12 April 2000

This is a multi-site certification. Additional site details are listed on the subsequent page.

Authorised by



SGS United Kingdom Ltd Rossmore Business Park Ellesmere Port Cheshire CH65 3EN UK t +44 (0)151 350-6666 f +44 (0)151 350-6600 www.sgs.com

HC SGS 9001 2015 0818 M2

Page 1 of 2










SCSCS

This document is a Web version of SGS certificate for electronic use exclusively. It shall only be available by clicking on SGS Certification Mark which has been posted on Your website. It shall not be printed in anyway. This document is copyright protected. No content or appearance may be reproduced without the express written permission of SGS. Any misuse, alteration, forgery or falsification is unlawful.



Certificate SG00/00050, continued





PT Venturindo Jayas Batam

ISO 9001:2015



Issue 11

Detailed scope

1. PCBA, Precision Mechanism Assembly and Injection Moulding
2. Design and Manufacturing of Flexible Flat Cable

Additional facilities

B2, Lot 4, Panbil Industrial Estate Muka Kuning, Pulau Batam 29433 Indonesia





This document is a Web version of SGS certificate for electronic use exclusively. It shall only be available by clicking on SGS Certification Mark which has been posted on Your website. It shall not be printed in anyway. This document is copyright protected. No content or appearance may be reproduced without the express written permission of SGS. Any misuse, alteration, forgery or falsification is unlawful.